

A1/275/26-27. TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer / Assistant Executive Engineer)

- Name of School *Synergy Hill valley public school*
Koorachundu.
1. Name of the Officer *Jeena. K.*
2. Location *Koorachundu.*
3. Period for which the certificate is issued *2026-27. I Building*
4. Types of building *I Building*
GF) 6.12 x 6.08 x 3.63 (2) FF) 6.12 x 6.08 x 3.63 (2)
6.12 x 6 x 3.63 (2) 6.12 x 6 x 3.63 (2)
6.12 x 6.14 x 3.63 (2) 6.12 x 6.14 x 3.63 (2)
5. Nature of defect if any
- a) Foundation and basement *II Building*
GF) 6.4 x 6.28 x 3.63 (1) FF) 6.4 x 6.28 x 3.63 (1)
6.16 x 6.28 x 3.63 (1) 6.16 x 6.28 x 3.63 (1)
6.14 x 6.3 x 3.63 (1) 6.14 x 6.3 x 3.63 (1)
6.2 x 6.3 x 3.63 (1) 6.2 x 6.3 x 3.63 (1)
- b) Superstructure
- c) Doors and Windows *SF) 6.33 x 6.28 x 3.63 (1)*
6.05 x 6.42 x 3.63 (1)
6.49 x 6.42 x 3.63 (1)
6.16 x 6.28 x 3.63 (1)
- d) Wood work wrought and put up *Nil*
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks if any)
6. Any major defects noticed which will render the building unsafe in any manner *Nil*
7. Whether maintenance work have been done properly *Yes*
8. Whether the structure is sound or not for conducting classes. *The structure is sound for conducting classes under normal weather conditions*
- Note: 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
- 2 Any additional observation deemed necessary for the Certificate, may be furnished separately with the Certificate.

Certified that the School was inspected by me on *23/09/26* and found to be, **fit / unfit** to conduct classes for the period for the reasons stated above

Place: *Balussery*

Date: *25/09/26*



Signature

Designation

[Signature]
ASSISTANT EXECUTIVE ENGINEER,
LSGD (UD & EW) Sub Division
Balussery Block Panchayath
Kozhikode